

Figure 5-17a
Predicted Shear Stress for 100-Year Flow and Seiche - OU 4 Existing Conditions
Lower Fox River