

Wednesday, December 29, 1999 06:53:39 Page: 1

Grid Volume Report

Original Surface: Original hard bottom + phase 2 hard bottom
Design Surface: Phase 2 post-dredge survey

Total Remaining Sediment (c.y.)
2,834

FOX RIVER - DEPOSIT "N" - KIMBERLY, WI.

FIGURE 16
SEDIMENT THICKNESS AFTER PHASE II DREDGING

Scale: 0 50' 100'

Date: APRIL, 2001

Prepared By: **Foth & Van Dyke** By: JRB2 97W027

I:\97W027\7w27f57.3d 04/18/2001 04:53:25 PM