

## Deposit POG1 B, Phase 2 Post-Construction Status Report – August 2007

**Purpose:** Comply with Wisconsin Department of Natural Resources (WDNR) conditional work plan approval for remediation of Deposit POG1 B, dated September 11, 2006. The conditional work plan approval required monthly reports following construction activities to remediate Deposit POG1 B. The monthly reports must document the condition of the erosion control measures and any required maintenance activities. The monthly reports must be submitted the first week of each month until the area is re-vegetated and stable.

The construction at Deposit POG1 B was completed on November 3, 2006. A summary of construction activities was submitted to Ms. Kristy Rogers of the WDNR on November 29, 2006. This constitutes the August 2007 monthly post-construction report.

**Observations:** The area of Deposit POG1 B was observed by STS on August 31, 2007. On this date the lake level was at about +736.6, about 1.5 feet below normal pool level. The shore zone and slope were stable. Site conditions on August 31, 2007 are shown in Photographs 1 and 2. Recent precipitation promoted vegetative growth. The slope was dominated by common ragweed; however, there was an under-story of new growth, which included desired species such as black-eyed Susan, goldenrod, vervain, lobelia, cinquefoil and coneflowers. The shore area had a significant smartweed cover. The shallow water area was filling in naturally, as shown in Photograph 1.

In August the fence along the pedestrian walkway was removed. No site work is proposed for September 2007 and G.W. Partners requests suspension of monthly post-construction status reports until April 2008. Four post-construction reports are proposed for 2008, including April, May, June and August/September.

Photograph 1 – Shoreline looking north from pedestrian bridge.



Photograph 2 – Slope condition at the northern end of the site, looking north.



**Prepared by:** Steven Shimek, STS