

## Deposit POG1 B, Phase 2 Post-Construction Status Report – June 2007

**Purpose:** Comply with Wisconsin Department of Natural Resources (WDNR) conditional work plan approval for remediation of Deposit POG1 B, dated September 11, 2006. The conditional work plan approval required monthly reports following construction activities to remediate Deposit POG1 B. The monthly reports must document the condition of the erosion control measures and any required maintenance activities. The monthly reports must be submitted the first week of each month until the area is re-vegetated and stable.

The construction at Deposit POG1 B was completed on November 3, 2006. A summary of construction activities was submitted to Ms. Kristy Rogers of the WDNR on November 29, 2006. This constitutes the June 2007 monthly post-construction report.

**Observations:** The area of Deposit POG1 B was observed by STS on June 27, 2007. The lake level continued to be relatively low and the shoreline was below the seeded area. The slopes continued to be stable and did not show signs of erosion. The erosion control mats were starting to show signs of deterioration, as expected.

During the weeks of June 18 and 25, 2007, the silt fence was removed and the area was hydroseeded and mulched. Specific methods of completing the work and application rates will be provided in the July 2007 report. Observations will occur in July 2007 and will focus on the success of the recent re-seeding and mulching. The site will also be viewed for perennials seeded in late 2006.

Photograph 1 – Shoreline looking north from pedestrian bridge.



Photograph 2 – Slope conditions in the mid-section of the site, looking south.



Photograph 3 – Slope condition at the northern end of the site, looking north.



**Prepared by:** Steven Shimek, STS